H5MPB-110 Connector

for HELIAX®HJ5-50 Coaxial Cable



Description

This connector is designed for tab-flaring of the outer conductor and self-tapping (thread cutting) of the inner conductor of the coaxial cable. It can be installed either as gas pass or gas block, depending on which of the two insulators provided is used.

Tools and Materials Required for Assembly

Knife Flat file Metal snips Plastic head mallet Plastic rod

Screw driver Hacksaw: fine-toothed blade Wrenches:


(1) 5/16"

(2) 2-3/4" monkey wrench


Prepare the cable as shown and make certain that the cable end is square. Use a straightedged piece of paper wrapped around the cable to guide the knife when cutting the jacket. File the cut edges of the conductors to remove rough spots and deburr the end of the inner conductor. Hold the cable downward and tap lightly to remove particles.




Screw the clamping nut onto the cable. Unscrew the clamping nut and mark the position at which the nut comes off the cable. This is the reference point for starting the clamping nut back onto the cable. Apply a thin coating of silicone grease to the threaded gasket and the inner surface of the clamping nut. Position the gasket to within 1/8" of the cable jacket. Screw the gasket onto the outer conductor as shown.



Align the pencil marks and push the clamping nut over the gasket. Screw the nut into place so that the outer conductor is slightly exposed as shown. This action pulls the gasket into the correct position. Wipe the silicone grease off the exposed outer conductor and cut tabs as shown.



Flare the tabs of the outer conductor against the edge of the clamping nut by lightly tapping them with the rod and mallet. Use only enough force to flatten the tabs. Trim tab ends that protrude beyond the edge of the clamping nut.




Trim, file, and deburr the inner conductor so that it is flush with the flared outer conductor before inserting the inner stub.

Screw the inner stub, while firmly pushing inward, into the inner conductor. Use a 5/16" wrench to turn the inner stub and apply solvent to the threads as a lubricant.

For gas pass application, select the insulator with a hole; for gas barrier application, select the solid insulator.

Verify that the preassembled small O-ring is present inside the insulator. Apply a thin coating of silicone grease to the small O-ring.


Place the spacer against the clamping nut and the insulator on the stub against the spacer. Screw the contact sleeve onto the inner stub finger tight. Lock the contact sleeve in place by inserting a lock nut into the sleeve and stub. Tighten the lock nut with a screwdriver. Do not overtighten. The spacer is designed to be loose and rotate freely.



Spacer is designed to be

loose and rotate freely

Apply a thin coating of silicone grease to the Orings. Slide the large O-ring into the groove of the clamping nut. Position the outer body over the insulator and spacer and screw the outer body onto the clamping nut. Tighten the connection with wrenches.



Hold the clamping nut and turn only the outer body to 40-44 lb-ft (54-60 N·m).



Installation Tip: Scratch "Pass" or "Block" on the outer body with a screw driver to indicate whether you installed the H5MPB-110 connector as gas pass or gas block.

Notice

Large

O-ring

The installation, maintenance or removal of antenna systems requires qualified, experienced personnel. Andrew installation instructions are written for such personnel. Antenna systems should be inspected once a year by qualified personnel to verify proper installation, maintenance and condition of equipment.

Andrew disclaims any liability or responsibility for the results of improper or unsafe installation practices.



Customer Service, 24 hours: U.S.A. • Canada • Mexico: 1-800-255-1479