

Feb 2017 Rev H


Don't Connect Unless You Inspect!






Simplex Parallel Dress Clip (Available Separately)

Duplex Parallel Dress Clip (Available Separately)





MT-RJ JACK KIT		OPTICAL FIBER SIZE ●		
TYPE	DESCRIPTION	50/125 μm	62.5/125 µm	XG 50/125 μm
Patch Panel	Standard Jacks	6588880-1	6588880-2	6588880-3
	MT-RJ SECURE® Jacks	6588879-[]	6588878-[]	6693949-[]
Workstation	Standard Jacks	6278414-[]*	6278415-[]	1-6278414-2
	MT-RJ SECURE Jacks	6278811-[]	6278810-[]	6754252-[]

The fiber optic size is marked on the rear underside of the lack module assembly. Size 50/125 is indicated as "50," Size 62.5/125" is indicated as "62," and Size "XG 50/125" is indicated as "XG."

Figure 1

1. INTRODUCTION

The MT-RJ jack kits listed in Figure 1 are designed to terminate 900-um tight bu ered optical ber. The jacks must be used with 125-µm multimode ber optic cable only. Read these instructions thoroughly before assembling the jack kits.



These jack kits cannot be used with build-up tubes, loose tube fiber, easy-strip fiber, fan-out kits, or breakout kits.



Dimensions in this instruction sheet are in metric units [with U.S. customary units in brackets]. Figures are not drawn to scale.

Reasons for reissue of this instruction sheet are provided in Section 6, REVISION SUMMARY.

The patch panel jacks t into adapter plates or patch panels for use in a rack- or wall-mount enclosures or enclosures having an adapter plate or patch panel.

^{*} Except -12



The workstation jacks can be used in faceplates or wall outlets for use on wall boxes that are at least 50.8 mm [2 in.] deep. The workstation jacks can be installed using the SL jack housing (included with the kit) or Parallel Dress Clip 1374206-1 (simplex) or 1374205-1 (duplex) shown in Figure 1.



For available adapter plates, patch panels, enclosures, faceplates and wall outlets, and installation instructions, refer to 408-8844.

2. **DESCRIPTION** (Figure 1)

Each patch panel jack kit contains six MT-RJ jack module assemblies (each with protective cover), an icon wheel, 900-µm ber guide (black), and two actuation keys.

Each workstation jack kit contains one MT-RJ jack module assembly (with protective cover), SL jack housing, 900-µm (black) ber guide, jack boot, and an actuation key.



The jack kits are shipped with the protective covers installed onto the jacks. Keep protective covers in place until ready for connection.

Each jack has two channels designated (on the top of the jack) with "A" and "B."

3. ASSEMBLY PROCEDURE



ALWAYS wear eye protection when working with optical fibers. NEVER look into the end of terminated or unterminated fibers. Laser radiation is invisible but can damage eye tissue.



NEVER eat, drink, or smoke when working with fibers. This could lead to ingestion of glass particles.



During assembly, keep kit components and tools as clean as possible to avoid contamination in the optical interface.

3.1. Tools and Materials

The following tools and materials are necessary for preparation, assembly, inspection, and maintenance of the assembly. Follow the operating instructions (408-series) packaged with the tools and safety guidelines packaged with the materials.

A. Required

 Fiber Optic Combination Strip Tool 1278947-1 (408-4577) or 1754708-1

- Micro-Strip Strip Tool 492109-2 (for 900- μm bu ered ber)
- Alcohol Fiber Wipe Packet 501857-2 or lint-free tissues and isopropyl alcohol greater than 91% (99% preferred)
- Fiber Optic Cleaver 1871696-1 (408-10086)



The above items are included in MT-RJ Jack Termination Kit 1278346-1 and LightCrimp Plus® and MT-RJ Jack Combination Termination Kit 1278118-4.

- Canned air (commercially available)
- Test Kit (408-4579):

TEST KIT	OPTICAL FIBER	TEST EQUIPMENT CONNECTOR INTERFACE		
1278861-1	50/125-µm Multimode	SC		
1278861-2	50/125-µm Multimode	Straight Tip (ST) Style		
1278862-1	62.5/125-µm Multimode	SC		
1278862-2	62.5/125-µm Multimode	ST Style		
1278863-1	Singlemode	SC		
1278863-2	Singlemode	ST Style		

B. Optional

- Visual Fault Locator 1828352-1
- Bare Fiber Adapter 934-125 (available from RIFOCS™)
- 200¢ Microscope Kit 1754767-1
- 2.5mm Universal Adapter 1754766-1 (included with microscope)
- MT-RJ Microscope Adapter 1754768-1 (use with microscope)

3.2. Preparation

A. Stripping the Cable

1. For workstation jacks, slide the jack boot (small diameter end rst) onto the ber.

IMPORTANT — For correct system polarity, Channel "A" must be connected to Channel "B" and Channel "B" must be connected to Channel "A" on any cable run or cable assembly (including fiber optic equipment). Refer to Figure 2.

- 2. Using the ber optic combination strip tool, strip the cable jacket to expose approximately 381 to 508 mm [15 to 20 in.] o ber. Trim the strength members even with the jacket.
- 3. Using the micro-strip strip tool, strip the ber to 35 to 37 mm [1.38 to 1.46 in.].

2 of 6 Rev H



Panel Workstation




Figure 2

4. Clean the stripped portion of the ber with an alcohol ber wipe or lint-free tissue moistened with isopropyl alcohol greater than 91% (99% preferred) to remove the ber coating residue. DO NOT touch the stripped portion of the ber after cleaning.


B. Cleaving the Fiber



Fibers must be terminated as soon as the cleaving and inspection process is complete; otherwise, damage to the fibers could result.

- 1. Open the ber clamp of the ber optic cleaver. Press the button, and slide the carriage back (toward the ber clamp). Then move the ber slide back until it stops.
- 2. Place the stripped ber into the slot so that the end of the bu er is at the 6-mm marking. See Figure 3, Detail A.
- 3. While applying pressure on the bu er, carefully slide the ber slide forward (toward the carriage) until it stops. See Figure 3, Detail B.
- 4. Gently close the ber clamp, and slide the carriage forward. DO NOT touch the button while sliding the carriage. See Figure 3, Detail C.
- 5. Open the ber clamp, and move the ber slide back until it stops.
- 6. Remove the cleaved ber, and properly dispose of the scrap ber. If the ber does not cleave, repeat the process starting with Step 3 of Paragraph 3.2.A.

Detail B



End of Buffer at 6-mm Marking


Detail B



Slide Fiber Slide Forward

Detail C

Fiber Clamp Closed



Slide Carriage Forward

Figure 3



Be careful to dispose of fiber ends properly. The fibers create slivers that can easily puncture skin and cause irritation.

Rev H 3 of 6





Fibers must have a quality cleave before terminating to the jacks. To ensure that the cleave tool is producing quality cleaves, it is STRONGLY RECOMMENDED to inspect at least one fiber cleave per day according to the following:

- 1. Fit the bare fiber adapter onto the universal adapter; then assemble the universal adapter onto the microscope.
- 2. Using the microscope, inspect the fiber for a quality cleave. Refer to the instructions packaged with the microscope kit) for operating procedures and safety precautions concerning the microscope.



DO NOT attempt to clean the fiber after it has been cleaved.

IMPORTANT — Fibers must be terminated as soon as the cleaving and inspection process is complete; otherwise, damage to the fibers could result. Procedd to Paragraph 3.3.

3.3. Termination



DO NOT use build-up tubes, fan-out kits, or breakout kits on the fibers, and DO NOT use loose tube fiber easy-strip fiber.

IMPORTANT —For correct system polarity, Channel "A" must be connected to Channel "B" and Channel "B" must be connected to Channel "A" on any cable run or cable assembly (including fiber optic equipment). Refer to Figure 2.

Proceed as follows:

1. Holding the jack or placing the jack on a clean, at surface (the protective cover helps to keep the jack stabilized), slide the ber guide onto the back of the jack. See Figure 4.



The fiber guide is marked with the fiber size. Make sure that the marking on the fiber guide corresponds with the fiber size being used.





Figure 4

- 2. With the handle of the actuation key pointed toward the top of the jack, insert the key (pointed end rst) into the key hole for Channel A until it stops (the entire key portion must be inside the hole). See Figure 5. DO NOT force the key. With the key in this position, the ber hole is "closed."
- 3. Slide the prepared ber onto the slot of the ber guide and into the ber hole until the ber stops. Refer to Figure 5.
- 4. While lightly holding the ber in place, *SLOWLY* rotate the key handle 90° (one-quarter turn) toward the outside of the jack. See Figure 6, Detail B. With the key in this position, the ber hole is "open."



Ensure that the key is rotated ONLY one-quarter turn; otherwise, the fiber hole will be partially open, and the fiber cannot be inserted.






Figure 5

4 of 6 Rev H



Detail B

Key in Position—
Fiber Hole is "Open"






Figure 6

- 5. Insert the ber further into the ber hole until it bottoms. See Figure 7, Detail A. If the ber stubs while inserting it into the ber hole, slightly turn the ber, and continue to insert the ber into the hole. The ber is fully inserted into the ber hole when the stripped portion of the ber is inside the jack.
- 6. Hold the ber in place using enough pressure to create a slight bow in the ber, then *SLOWLY* rotate the key handle 90° (one-quarter turn) toward the inside of the jack. DO NOT " ip" the key handle. Refer to Figure 7, Detail B. The ber is now terminated to the jack.
- 7. Remove the key from the jack.



If preferred, use the visual fault locator to confirm that the fiber is fully inserted into the fiber hole. When the fiber is properly inserted, the laser (or LED) light will diminish in the target area of the jack. Refer to Figure 8.




If using the visual fault locator, avoid contamination to the ferrule end face. Make sure that the protective cover remains clean when removed, and then before proceeding, re-install the protective cover onto the jack.

If the ferrule end face is touched or otherwise contaminated, clean the end face with canned air before re-installing the protective cover. TO AVOID PERSONAL INJURY, wear eye protection.

8. Repeat the assembly procedure for Channel B.

Detail A



Insert Fiber into Fiber Hole

Detail BRotate Key to Terminate Fiber to Jack






Figure 7

Using Visual Fault Locator (Optional)




Figure 8

Rev H 5 of 6



9. Carefully slide the ber guide at least 76 mm [3 in.] away from the jack, then carefully route the ber out of the slot in the ber guide. Keep the protective cover on the jack if not installing the jack immediately.



To avoid tension on the fiber, it is important to slide the fiber guide away from the jack before routing the fiber out of the fiber guide.

10. For workstation jacks, check to make sure that the bers are not twisted, then slide the jack boot over the element housing of the jack until it butts against the shoulder. See Figure 9.



It is important that the FIBERS ARE NOT TWISTED before installing the jack boot.

Jack Boot Installed onto Workstation Jack




Figure 9


3.4. Inspection

Remove the protective cover, and inspect the ferrule end face for cleanliness using the microscope kit.

3.5. Installation

Refer to Instruction Sheet 408-8844 for instructions on installing the jacks into the adapter plates, patch panels, or enclosure or wall box.

Don't Connect Unless You Inspect!



DANGER: Never View Active Fiber Signals

4. TESTING

Test the system a trenuation and polarity using the applicable test kit listed in Paragraph 3.1.A. Refer to 408-4579 (packaged with the test kit) for instructions on using the test kit and testing procedures.

5. REPLACEMENT AND REPAIR

Jack kit components are not repairable. Replace any damaged or defective components.

6. REVISION SUMMARY

Revisions to this instruction sheet include:

- Updated document to corporate requirements
- New logo
- Rebranded to CommScope

6 of 6 Rev H